

0003



Sunnyside Cogeneration Associates

P.O. Box 10, East Carbon, Utah 84520 • (435) 888-4476 • Fax (435) 888-2538

January 24, 2000

Daron Haddock
STATE OF UTAH
Division of Oil, Gas & Mining
1594 W. North Temple, Suite 1210
P. O. Box 145801
Salt Lake City, Utah 84114-5801

RE: Fourth Quarter 1999 Inspection Report

Dear Mr. Haddock:

Please find enclosed a copy of the Fourth Quarter 1999 Inspection Report for Sunnyside Cogeneration Associates' impoundments, refuse pile and excess spoil areas. The inspection was performed by a professional engineer from Psomas and Associates Engineering.

Should you have any questions, please contact me at (435) 888-4476.

Sincerely,

Agent For
Sunnyside Cogenerations Associates

Rusty Netz

Rusty Netz
Environmental Coordinator

Enclosure

c.c. Bill Malencik/Division of Oil, Gas & Mining
Plant File

*Sheila -
That King
FAX Cover Letter
to Bill @
PFD*

*ACT/007/035
Put in
Incoming*

RECEIVED

JAN 27 2000

**DIVISION OF
OIL, GAS AND MINING**

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT		Clear Water Pond	
Permit Number	ACT/007/035	Report Date 12/30/99	
Mine Name	SUNNYSIDE REFUSE AND SLURRY		
Company Name	SUNNYSIDE COGENERATION ASSOCIATES		
Impoundment Identification	Impoundment Name	Clear Water Pond	
	Impoundment Number	004	
	UPDES Permit Number	UT 024759	
	MSHA ID Number	N/A	
IMPOUNDMENT INSPECTION			
Inspection Date	12/22/99		
Inspected By	Scott Carlson		
Reason for Inspection (Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction)		Fourth Quarter Inspection 1999	
<p>1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.</p> <p>NONE</p>			
Required for an impoundment which functions as a SEDIMENTATION POND.	<p>2. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and, estimated average elevation of existing sediment.</p> <p>Storage Capacity = 4.9 acre-feet Maximum Sediment Depth Elevation = 6527 Existing Sediment Elevation = 6523+-</p>		
	<p>3. Principle and emergency spillway elevations.</p> <p>Spillway Elevation = 6530.1</p>		

RECEIVED
JAN 27 2000
DIVISION OF
OIL, GAS AND MINING

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Clear Water Pond

4. **Field Information.** Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/instrumentation information, inlet/outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/repairs, monitoring information, vegetation on outslopes of embankments, etc.

No discharge, inlet/outlet conditions are good,
no structural or hazardous conditions exist.

5. **Field Evaluation.** Describe any changes in the geometry of the impounding structure, average and maximum depths and elevations of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period.

Pond was dry.

No structure or stability problems observed.

Reclamation of the Sunnyside Coal Property is currently underway. Among the facilities being reclaimed is the Slurry Ditch which connected to the SCA Properties. This ditch has been filled in near the SCA Property and is no longer a major storm water conveyance facility to the Slurry Ponds #1 and #2 or to the Clearwater Pond or to the East Slurry Cell. Watersheds which previously contributed to these ponds are no longer doing so.

In accordance with the approved plan to construct the Excess Spoil Disposal area #2, the Slurry Ponds #1 and #2 no longer receive storm runoff. These storm flows are now routed directly to either the East Slurry Cell or to the Clear Water Pond. With the reclamation activities at Sunnyside Coal, both of these ponds have ample capacity to handle the stormflows without the Slurry Ponds in series.


**Qualification
Statement**

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

Signature: _____

Scott Carlson

Date: 12/30/99

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT	Clear Water Pond	
CERTIFIED REPORT		
IMPOUNDMENT EVALUATION (If NO, explain under Comments)	YES	NO
1. Is impoundment designed and constructed in accordance with the approved plan?	yes	
2. Is impoundment free of instability, structural weakness, or any other hazardous condition?	yes	
3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection?	yes	
COMMENTS AND OTHER INFORMATION		
None		
Certification Statement: 	I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.	
	By: <u>S. Scott Carlson</u> Project Manager (Full Name and Title)	
	Signature: <u><i>S. Scott Carlson</i></u> Date: <u>12/30/99</u>	
	P.E. Number & State: <u>187727 UT</u>	

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT		Railcut Pond	
Permit Number	ACT/007/035	Report Date 12/30/99	
Mine Name	SUNNYSIDE REFUSE AND SLURRY		
Company Name	SUNNYSIDE COGENERATION ASSOCIATES		
Impoundment Identification	Impoundment Name	Railcut Sediment Pond	
	Impoundment Number	007	
	UPDES Permit Number	UT 024759	
	MSHA ID Number	N/A	
IMPOUNDMENT INSPECTION			
Inspection Date	12/22/99		
Inspected By	Scott Carlson		
Reason for Inspection (Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction)		Fourth Quarter Inspection 1999	
<p>1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.</p> <p>NONE</p>			
Required for an impoundment which functions as a SEDIMENTATION POND.	<p>2. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and, estimated average elevation of existing sediment.</p> <p>Storage Capacity = 4.8 acre-feet Maximum Sediment Depth Elevation = 6207.7 Estimated Existing Sediment Elevation = 6207+-</p>		
	<p>3. Principle and emergency spillway elevations.</p> <p>Spillway Elevation = 6212.34 Primary Drain Elevation = 6209.07</p>		

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Railcut Pond

4. **Field Information.** Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/instrumentation information, inlet/outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/repairs, monitoring information, vegetation on outslopes of embankments, etc.

No discharge, inlet/outlet conditions are good,
no structural or hazardous conditions exist.

5. **Field Evaluation.** Describe any changes in the geometry of the impounding structure, average and maximum depths and elevations of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period.


No changes. Pond was dry. No structure or stability problems observed.

**Qualification
Statement**

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

Signature: _____

Date: 12/30/99

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT		Railcut Pond	
CERTIFIED REPORT			
IMPOUNDMENT EVALUATION (If NO, explain under Comments)		YES	NO
1. Is impoundment designed and constructed in accordance with the approved plan?		yes	
2. Is impoundment free of instability, structural weakness, or any other hazardous condition?		yes	
3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection?		yes	
COMMENTS AND OTHER INFORMATION			
None			
Certification Statement:		I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.	
		By: <u>S. Scott Carlson, P.E. Project Manager</u> Signature: <u><i>S. Scott Carlson</i></u> Date: <u>12/30/99</u> P.E. Number & State: <u>187727 - UT</u>	

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT		OCRR Pond	
Permit Number	ACT/007/035	Report Date 12/30/99	
Mine Name	SUNNYSIDE REFUSE AND SLURRY		
Company Name	SUNNYSIDE COGENERATION ASSOCIATES		
Impoundment Identification	Impoundment Name	Old Coarse Refuse Road Sediment Pond	
	Impoundment Number	008	
	UPDES Permit Number	UT 024759	
	MSHA ID Number	N/A	
IMPOUNDMENT INSPECTION			
Inspection Date	12/22/99		
Inspected By	Scott Carlson		
Reason for Inspection (Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction)		Fourth Quarter Inspection 1999	
<p>1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.</p> <p>NONE</p>			
Required for an impoundment which functions as a SEDIMENTATION POND	<p>2. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and, estimated average elevation of existing sediment.</p> <p>Storage Capacity = 0.9 acre-feet Maximum Sediment Depth Elevation = 6394.75 Estimated Existing Sediment Elevation = 6394+-</p>		
	<p>3. Principle and emergency spillway elevations.</p> <p>Spillway Elevation = 6399.4 Primary Drain Elevation = 6395.75</p>		

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

OCRR Pond

4. **Field Information.** Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/instrumentation information, inlet/outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/repairs, monitoring information, vegetation on outslopes of embankments, etc.

No discharge, pond was dry, inlet/outlet conditions are good,
No structural or hazardous conditions exist.


5. **Field Evaluation.** Describe any changes in the geometry of the impounding structure, average and maximum depths and elevations of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period.


No changes, no structure or stability problems observed.

Qualification Statement

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

Signature: _____

Date: 12/30/99

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT		OCRR Pond	
CERTIFIED REPORT			
IMPOUNDMENT EVALUATION (If NO, explain under Comments)	YES	NO	
1. Is impoundment designed and constructed in accordance with the approved plan?	yes		
2. Is impoundment free of instability, structural weakness, or any other hazardous condition?	yes		
3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection?	yes		
COMMENTS AND OTHER INFORMATION			
<div style="margin-left: 40px;">none</div>			
Certification Statement:	<p>I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.</p>		
	<p>By: <u>S. Scott Carlson, P.E. Project Manager</u></p> <p>Signature: <u><i>S. Scott Carlson</i></u> Date: <u>12/30/99</u></p> <p>P.E. Number & State: <u>187727 - UT</u></p>		

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT		Pasture Pond	
Permit Number	ACT/007/035	Report Date 12/30/99	
Mine Name	SUNNYSIDE REFUSE AND SLURRY		
Company Name	SUNNYSIDE COGENERATION ASSOCIATES		
Impoundment Identification	Impoundment Name	Pasture Sediment Pond	
	Impoundment Number	009	
	UPDES Permit Number	UT 024759	
	MSHA ID Number	N/A	
IMPOUNDMENT INSPECTION			
Inspection Date	12/22/99		
Inspected By	Scott Carlson		
Reason for Inspection (Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction)		Fourth Quarter Inspection 1999	
<p>1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.</p> <p>NONE</p>			
Required for an impoundment which functions as a SEDIMENTATION POND	<p>2. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and, estimated average elevation of existing sediment.</p> <p>Storage Capacity = 1.0 acre-feet Maximum Sediment Depth Elevation = 6485.5 Estimated Existing Sediment Elevation = 6484+-</p>		
	<p>3. Principle and emergency spillway elevations.</p> <p>Spillway Elevation = 6490.6 Primary Drain Elevation = 6486.6</p>		

Pond was dry.
No discharge, inlet/outlet conditions are good,
No structural or hazardous conditions exist.


No changes. No structure or stability problems observed.

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

Signature:

e: Scott Carlson

Date: 12/30/99

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT		Pasture Pond	
CERTIFIED REPORT			
IMPOUNDMENT EVALUATION (If NO, explain under Comments)	YES	NO	
1. Is impoundment designed and constructed in accordance with the approved plan?	yes		
2. Is impoundment free of instability, structural weakness, or any other hazardous condition?	yes		
3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection?	yes		
COMMENTS AND OTHER INFORMATION			
<p style="margin-left: 40px;">none</p>			
Certification Statement:	<p>I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.</p>		
	<p>By: <u>S. Scott Carlson - Project Manager</u></p> <p>Signature: <u><i>S. Scott Carlson</i></u> Date: <u>12/30/99</u></p> <p>P.E. Number & State: <u>187727 - UT</u></p>		

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT		CRT Pond	
Permit Number	ACT/007/035	Report Date 12/30/99	
Mine Name	SUNNYSIDE REFUSE AND SLURRY		
Company Name	SUNNYSIDE COGENERATION ASSOCIATES		
Impoundment Identification	Impoundment Name	New Coarse Refuse Toe Sediment Pond	
	Impoundment Number	012	
	UPDES Permit Number	UT 024759	
	MSHA ID Number	N/A	
IMPOUNDMENT INSPECTION			
Inspection Date	12/22/99		
Inspected By	Scott Carlson		
Reason for Inspection (Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction)		Fourth Quarter Inspection 1999	
<p>1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.</p> <p>NONE</p>			
Required for an impoundment which functions as a SEDIMENTATION POND	<p>2. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and, estimated average elevation of existing sediment.</p> <p>Storage Capacity = 1.6 acre-feet Maximum Sediment Depth Elevation = 6177.0 Estimated Existing Sediment Elevation = 6176+-</p>		
	<p>3. Principle and emergency spillway elevations.</p> <p>Spillway Elevation = 6183.63 Primary Drain Elevation = 6178.2</p>		

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

CRT Pond

4. **Field Information.** Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/instrumentation information, inlet/outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/repairs, monitoring information, vegetation on outslopes of embankments, etc.

Pond was dry.

No discharge, inlet/outlet conditions are good,


No structural or hazardous conditions exist.

5. **Field Evaluation.** Describe any changes in the geometry of the impounding structure, average and maximum depths and elevations of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period.

No changes. No structure or stability problems observed.

**Qualification
Statement**

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.



Signature: _____

S. Scott Carlson

Date: 12/30/99

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

CRT Pond

CERTIFIED REPORT


IMPOUNDMENT EVALUATION (If NO, explain under Comments)	YES	NO
1. Is impoundment designed and constructed in accordance with the approved plan?	yes	
2. Is impoundment free of instability, structural weakness, or any other hazardous condition?	yes	
3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection?	yes	

COMMENTS AND OTHER INFORMATION

None

Certification
Statement:

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: S. Scott Carlson - Project ManagerSignature: S. Scott CarlsonDate: 12/30/99P.E. Number & State: 187727 - UT

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT		COAL RUNOFF POND	
Permit Number	ACT/007/035	Report Date 12/30/99	
Mine Name	SUNNYSIDE REFUSE AND SLURRY		
Company Name	SUNNYSIDE COGENERATION ASSOCIATES		
Impoundment Identification	Impoundment Name	Coal Runoff Sediment Pond	
	Impoundment Number	014	
	UPDES Permit Number	UT 024759	
	MSHA ID Number	N/A	
IMPOUNDMENT INSPECTION			
Inspection Date	12/22/99		
Inspected By	Scott Carlson		
Reason for Inspection (Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction)		Fourth Quarter Inspection 1999	
<p>1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.</p> <p>NONE</p>			
Required for an impoundment which functions as a SEDIMENTATION POND	<p>2. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and, estimated average elevation of existing sediment.</p> <p>Storage Capacity = 1.5 acre feet Maximum Sediment Depth Elevation = 6476.0 Estimated Existing Sediment Elevation = 6474±</p>		
	<p>3. Principle and emergency spillway elevations.</p> <p>Spillway Elevation = 6477.9 Emergency Spillway Elevation = 6479.0</p>		

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

COAL RUNOFF POND

4. **Field Information.** Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/instrumentation information, inlet/outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/repairs, monitoring information, vegetation on outslopes of embankments, etc.

Pond had very little water in it.

No discharge, inlet and outlet conditions are good.

No structural or hazardous conditions exist.


5. **Field Evaluation.** Describe any changes in the geometry of the impounding structure, average and maximum depths and elevations of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period.

No changes.

No structure or stability problems observed.

**Qualification
Statement**


I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.



Signature: _____

S. Scott Carlson

Date: 12/30/99

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT	COAL RUNOFF POND	
CERTIFIED REPORT		
IMPOUNDMENT EVALUATION (If NO, explain under Comments)	YES	NO
1. Is impoundment designed and constructed in accordance with the approved plan?	yes	
2. Is impoundment free of instability, structural weakness, or any other hazardous condition?	yes	
3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection?	yes	
COMMENTS AND OTHER INFORMATION		
None		
Certification Statement: 	I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.	
	By: <u>S. Scott Carlson - Project Manager</u> <small>(Full Name and Title)</small>	
	Signature: <u><i>S. Scott Carlson</i></u>	Date: <u>12/30/99</u>
	P.E. Number & State: <u>187727 - UT</u>	

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT		Borrow Area Pond	
Permit Number	ACT/007/035	Report Date 12/30/99	
Mine Name	SUNNYSIDE REFUSE AND SLURRY		
Company Name	SUNNYSIDE COGENERATION ASSOCIATES		
Impoundment Identification	Impoundment Name	Borrow Area Pond	
	Impoundment Number	016	
	UPDES Permit Number	UT 024759	
	MSHA ID Number	N/A	
IMPOUNDMENT INSPECTION			
Inspection Date	12/22/99		
Inspected By	Scott Carlson		
Reason for Inspection (Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction)		Fourth Quarter Inspection 1999	
<p>1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.</p> <p>NONE</p>			
Required for an impoundment which functions as a SEDIMENTATION POND	<p>2. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and, estimated average elevation of existing sediment.</p> <p>Storage Capacity = 8.3 acre-feet Maximum Sediment Depth Elevation = 6513.3 Estimated Existing Sediment Elevation = 6511+-</p>		
	<p>3. Principle and emergency spillway elevations.</p> <p>Spillway Elevation = 6517.03 Primary Drain Elevation = 6514.3</p>		

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Borrow Area Pond

4. **Field Information.** Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/instrumentation information, inlet/outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/repairs, monitoring information, vegetation on outslopes of embankments, etc.

Pond was dry.

No discharge, inlet/outlet conditions are good,

No structural or hazardous conditions exist.

5. **Field Evaluation.** Describe any changes in the geometry of the impounding structure, average and maximum depths and elevations of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period.

No changes.

No structure or stability problems observed.


**Qualification
Statement**

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

Signature: _____

Scott Carlson

Date: 12/30/99

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT	Borrow Area Pond	
CERTIFIED REPORT		
IMPOUNDMENT EVALUATION (If NO, explain under Comments)	YES	NO
1. Is impoundment designed and constructed in accordance with the approved plan?	yes	
2. Is impoundment free of instability, structural weakness, or any other hazardous condition?	yes	
3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection?	yes	
COMMENTS AND OTHER INFORMATION		
<div style="margin-left: 40px;">none</div>		
Certification Statement: 	<p>I hereby certify that: I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.</p> <p>By: <u>S. Scott Carlson, P.E. Project Manager</u></p> <p>Signature: <u><i>S. Scott Carlson</i></u> Date: <u>12/30/99</u></p> <p>P.E. Number & State: <u>187727 Utah</u></p>	

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT		Slurry Pond #2	
Permit Number	ACT/007/035	Report Date 12/30/99	
Mine Name	SUNNYSIDE REFUSE AND SLURRY		
Company Name	SUNNYSIDE COGENERATION ASSOCIATES		
Impoundment Identification	Impoundment Name	Slurry Pond #2	
	Impoundment Number	N/A	
	UPDES Permit Number	N/A	
	MSHA ID Number	N/A	
IMPOUNDMENT INSPECTION			
Inspection Date	12/22/99		
Inspected By	Scott Carlson		
Reason for Inspection (Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction)		Fourth Quarter Inspection 1999	
<p>1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.</p> <p>NONE</p>			
Required for an impoundment which functions as a SEDIMENTATION POND	<p>2. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and, estimated average elevation of existing sediment.</p> <p>Storage Capacity = 15.3 acre-feet Maximum Sediment Depth Elevation = 6537.5 Estimated Existing Sediment Elevation = N/A</p>		
	<p>3. Principle and emergency spillway elevations.</p> <p>Top of Dike Elevation = 6540.1</p>		

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Slurry Pond #2

4. **Field Information.** Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/instrumentation information, inlet/outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/repairs, monitoring information, vegetation on outslopes of embankments, etc.

Pond was dry.
No discharge,
No structural or hazardous conditions exist.

5. **Field Evaluation.** Describe any changes in the geometry of the impounding structure, average and maximum depths and elevations of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period.

Slurry Pond is inactive, does not receive slurry from any source.

No structure or stability problems observed.

Reclamation of the Sunnyside Coal Property is currently underway. Among the facilities being reclaimed is the Slurry Ditch which connected to the SCA Properties. This ditch has been filled in near the SCA Property and is no longer a major storm water conveyance facility to the Slurry Ponds #1 and #2 or to the Clearwater Pond or to the East Slurry Cell. Watersheds which previously contributed to these ponds are no longer doing so.

In accordance with the approved plan to construct the Excess Spoil Disposal Area #2, the Slurry Ponds #1 and #2 no longer receive inflows of any storm waters. The inlet culverts have been removed and stormwater rerouted to other impoundments. SCA has begun to place spoil materials in Slurry Pond #1. No materials have yet been placed in Slurry Pond #2.

**Qualification
Statement**

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

Signature: _____

Scott Carlson

Date: 12/30/99

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Slurry Pond #2

CERTIFIED REPORT

IMPOUNDMENT EVALUATION (If NO, explain under Comments)

YES

NO

1. Is impoundment designed and constructed in accordance with the approved plan?

yes

2. Is impoundment free of instability, structural weakness, or any other hazardous condition?

yes

3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection?

yes

COMMENTS AND OTHER INFORMATION

Both Slurry Pond #1 and Slurry Pond #2 have been approved to be filled with coal mine waste and excess spoil in connection with construction of the Excess Spoil Disposal Area # 2.


The Clearwater Pond is also part of this disposal area but will continue to function as a sediment pond until such time as it is needed as a disposal site.

SCA is in the process of removing coal fines as they dry adequately for processing and are needed for fuel. Since SCA has begun to prepare this area for spoil materials and no longer uses it as a pond, we will no longer submit a report for the Slurry Pond #2. Please refer to the inspection report for Excess Spoil Disposal Area #2.

Certification Statement:

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: S. Scott Carlson - Project Manager
(Full Name and Title)

Signature: S. Scott CarlsonDate: 12/30/99P.E. Number & State: 187727 - UT

INSPECTION AND CERTIFIED REPORT ON EXCESS SPOIL PILE OR REFUSE PILE		Coarse Refuse Pile
Permit Number	ACT/007/035	Report Date 12/30/99
Mine Name	SUNNYSIDE REFUSE AND SLURRY	
Company Name	SUNNYSIDE COGENERATION ASSOCIATES	
Excess Spoil Pile or Refuse Pile Identification	File Name:	Coarse Refuse Pile
	File Number	N/A
	MSHA ID Number	1211-UT-09-02093-01
Inspection Date	12/22/99	
Inspected By	Scott Carlson	
Reason for Inspection (Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction)		Fourth Quarter Inspection 1999
		Attachments to Report? No <input checked="" type="checkbox"/> Yes
Field Evaluation		
1. Foundation preparation, including the removal of all organic material and topsoil.		
N/A		
2. Placement of underdrains and protective filter systems.		
N/A		
3. Installation of final surface drainage systems.		
N/A		
4. Placement and compaction of fill materials.		
N/A		
Removal of Coarse and fine Refuse Material Only		

5. Final grading and revegetation of fill.

N/A

6. Appearances of instability, structural weakness, and other hazardous conditions.

Excavation of refuse material damaged a small portion of the westerly access road around the refuse pile. The operator was notified and agreed to repair the road and adjacent ditch and berm.

7. Other Comments. Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period.

Waste Coal Removal

One Smoker was observed at the north edge of the pile. This was brought to the attention of the operator who indicated an intent to extinguish is immediately.

**Certification
Statement**

I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.


By: S. Scott Carlson - Project Manager
(Full Name and Title)

Signature: *S. Scott Carlson*

Date: 12/30/99

P.E. Number & State: 187727 - UT





Coarse Refuse Pile
12/22/99

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT		East Slurry Cell	
Permit Number	ACT/007/035	Report Date 12/30/99	
Mine Name	SUNNYSIDE REFUSE AND SLURRY		
Company Name	SUNNYSIDE COGENERATION ASSOCIATES		
Impoundment Identification	Impoundment Name	East Slurry Cell	
	Impoundment Number	N/A	
	UPDES Permit Number	N/A	
	MSHA ID Number	1211-UT-09-02093-02	
IMPOUNDMENT INSPECTION			
Inspection Date	12/22/99		
Inspected By	Scott Carlson		
Reason for Inspection (Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction)		Fourth Quarter Inspection 1999	
<p>1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.</p> <p>NONE</p>			
Required for an impoundment which functions as a SEDIMENTATION POND	<p>2. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and, estimated average elevation of existing sediment.</p> <p>Storage Capacity = 27+- acre-feet Maximum Sediment Depth Elevation = N/A Estimated Existing Sediment Elevation = N/A</p>		
	<p>3. Principle and emergency spillway elevations.</p> <p>N/A</p>		

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

East Slurry Cell

4. Field Information. Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/instrumentation information, inlet/outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/repairs, monitoring information, vegetation on out slopes of embankments, etc.

Pond surface was dry.

No structural or hazardous conditions exist.


5. Field Evaluation. Describe any changes in the geometry of the impounding structure, average and maximum depths and elevations of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period.

Slurry Cell is not receiving slurry from any source, currently functioning as a sediment pond. No structural or stability problems observed. Reclamation of the Sunnyside Coal Property is currently underway. Among the facilities being reclaimed is the Slurry Ditch which connected to the SCA Properties. This ditch has been filled in near the SCA Property and is no longer a major storm water conveyance facility to the Slurry Ponds #1 and #2 or to the Clearwater Pond or to the East Slurry Cell. Watersheds which previously contributed to these ponds are no longer doing so.

In accordance with the approved plan to construct the Excess Spoil Disposal area #2, the Slurry Ponds #1 and #2 no longer receive storm runoff. These storm flows are now routed directly to either the East Slurry Cell or to the Clear Water Pond. With the reclamation activities at Sunnyside Coal, both of these ponds have ample capacity to handle the stormflows without the Slurry Ponds in series.

Qualification Statement

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

Signature: 

Date: 12/30/99

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

East Slurry Cell

CERTIFIED REPORT

IMPOUNDMENT EVALUATION (If NO, explain under Comments)

YES

NO

1. Is impoundment designed and constructed in accordance with the approved plan?

yes

2. Is impoundment free of instability, structural weakness, or any other hazardous condition?

yes

3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection?


yes

COMMENTS AND OTHER INFORMATION

none

Certification
Statement:

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: S. Scott Carlson - Project Manager
(Full Name and Title)Signature: S. Scott CarlsonDate: 12/30/99P.E. Number & State: 187727 - UT

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT		West Cell	
Permit Number	ACT/007/035	Report Date 12/30/99	
Mine Name	SUNNYSIDE REFUSE AND SLURRY		
Company Name	SUNNYSIDE COGENERATION ASSOCIATES		
Impoundment Identification	Impoundment Name	West Slurry Cell	
	Impoundment Number	N/A	
	UPDES Permit Number	N/A	
	MSHA ID Number	1211-UT-09-02093-03	
IMPOUNDMENT INSPECTION			
Inspection Date	12/22/99		
Inspected By	Scott Carlson		
Reason for Inspection (Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction)		Fourth Quarter Inspection 1999	
<p>1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.</p> <p>NONE</p>			
Required for an impoundment which functions as a SEDIMENTATION POND	<p>2. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and, estimated average elevation of existing sediment.</p> <p>Storage Capacity = N/A Maximum Sediment Depth Elevation = N/A Estimated Existing Sediment Elevation = N/A</p>		
	<p>3. Principle and emergency spillway elevations.</p> <p>N/A</p>		

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

West Cell

4. **Field Information.** Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/instrumentation information, inlet/outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/repairs, monitoring information, vegetation on outslopes of embankments, etc.

Slurry Cell is Inactive
Refuse Removal

5. **Field Evaluation.** Describe any changes in the geometry of the impounding structure, average and maximum depths and elevations of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period.

Slurry Cell is not receiving slurry from any source

Excavation of refuse material damaged a small portion of the westerly access road around the refuse pile. The operator was notified and agreed to repair the road and adjacent ditch and berm.

Qualification Statement

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

Signature:



Date: 12/30/99

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

West Cell

CERTIFIED REPORT

IMPOUNDMENT EVALUATION (If NO, explain under Comments)

YES

NO

1. Is impoundment designed and constructed in accordance with the approved plan?

yes

2. Is impoundment free of instability, structural weakness, or any other hazardous condition?

yes

3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection?


yes

COMMENTS AND OTHER INFORMATION

none

Certification
Statement:

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: S. Scott Carlson - Project Manager
(Full Name and Title)

Signature:

Date: 12/30/99

P.E. Number & State: 187727 UT

INSPECTION AND CERTIFIED REPORT ON EXCESS SPOIL PILE OR REFUSE PILE		Excess Spoil Pile #1
Permit Number	ACT/007/035	Report Date 12/30/99
Mine Name	SUNNYSIDE REFUSE AND SLURRY	
Company Name	SUNNYSIDE COGENERATION ASSOCIATES	
Excess Spoil Pile or Refuse Pile Identification	File Name:	Excess Spoil Disposal Area #1
	File Number	N/A
	MSHA ID Number	1211-UT-09-02093-04
Inspection Date	12/22/99	
Inspected By	Scott Carlson	
Reason for Inspection (Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction)		Fourth Quarter Inspection 1999
		Attachments to Report? <input type="checkbox"/> No <input checked="" type="checkbox"/> Yes
Field Evaluation		
1. Foundation preparation, including the removal of all organic material and topsoil. N/A		
2. Placement of underdrains and protective filter systems. N/A		
3. Installation of final surface drainage systems. N/A		
4. Placement and compaction of fill materials. Received approximately 1,000 yards of spoils materials during this Quarter.		

5. Final grading and revegetation of fill.

N/A

6. Appearances of instability, structural weakness, and other hazardous conditions.

None

7. Other Comments. Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period.

Construction has been proceeding in shallow lifts in general conformance with the approved plan.

No evidence exists of fires in the pile.


**Certification
Statement**

I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

By: S. Scott Carlson - Project Manager
(Full Name and Title)

Signature: S. Scott Carlson Date: 12/30/99

P.E. Number & State: 187727 - UT





Excess Spoil Pile #1
12/22/99

INSPECTION AND CERTIFIED REPORT ON EXCESS SPOIL PILE OR REFUSE PILE		Excess Spoil Pile #2	
Permit Number	ACT/007/035	Report Date 12/30/99	
Mine Name	SUNNYSIDE REFUSE AND SLURRY		
Company Name	SUNNYSIDE COGENERATION ASSOCIATES		
Excess Spoil Pile or Refuse Pile Identification	Pile Name:	Excess Spoil Disposal Area #2	
	Pile Number	N/A	
	MSHA ID Number	1211-UT-09-02093-05	
Inspection Date	12/22/99		
Inspected By	Scott Carlson		
Reason for Inspection (Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction)		Fourth Quarter Inspection 1999	
		Attachments to Report? <input type="checkbox"/> No <input checked="" type="checkbox"/> Yes	
Field Evaluation			
<p>1. Foundation preparation, including the removal of all organic material and topsoil.</p> <p>Existing disturbed site. No topsoil removal is required by approved plan. SCA is currently in the process of removing accumulated coal fines from the Slurry Pond #2 area for use as fuel.</p>			
<p>2. Placement of underdrains and protective filter systems.</p> <p>Underdrains and filters are not required by approved plan. The Slurry Ponds #1 and #2 no longer receive inflows of any storm waters. The inlet culverts have been removed and stormwater rerouted to other impoundments.</p>			
<p>3. Installation of final surface drainage systems.</p> <p>N/A</p>			
<p>4. Placement and compaction of fill materials.</p> <p>Placement and compaction of fill material has begun in the portion of this disposal area formerly known as Slurry Pond #1. Material consists generally of coarse refuse rejects and is being placed in general conformance with the approved plan. Approximately 10,000 yards of material was placed during Third Quarter and 7,500 yards during the Fourth Quarter.</p>			

5. Final grading and revegetation of fill.

N/A

6. Appearances of instability, structural weakness, and other hazardous conditions.

None


7. Other Comments. Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period.

Both Slurry Pond #1 and Slurry Pond #2 have been approved to be filled with coal mine waste and excess spoil in connection with construction of the Excess Spoil Disposal Area # 2.

The Clearwater Pond is also part of this disposal area but will continue to function as a sediment pond until such time as it is needed as a disposal site.

Analytical results from samples taken of the material placed in this disposal area will be submitted with next quarter's report.

**Certification
Statement**



I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

By: S. Scott Carlson - Project Manager
(Full Name and Title)

Signature: S. Scott Carlson

Date: 12/30/99

P.E. Number & State: 187727 - UT



Excess Spoil Pile #2
12/22/99